




1/6



**FIG. 1A-1**




**FIG. 1A-2**

$PFC/PC = 0$




**FIG. 1B-1**



**FIG. 1B-2**

$PFC/PC = 1.1$



**FIG. 1C-1**




**FIG. 1C-2**

$PFC/PC = 2.2$

2/6




**FIG. 1D-1**



**FIG. 1D-2**

$PFC/PC = 4.8$




**FIG. 1E-1**




**FIG. 1E-2**

$PFC/PC = 18.8$



**FIG. 1F-1**



**FIG. 1F-2**

$PFC/PC = 44.7$

3/6






FIG. 2




**FIG. 3**

5/6



T = 0

FIG. 4A



30 Sec

FIG. 4B





FIG. 4C



2 Hrs

FIG. 4D




FIG. 5